

FIG. 1 (Prior Art)





FIG. 2

Capping Layer
20Å Co <sub>80</sub> Fe <sub>20</sub> or 40Å Ni <sub>80</sub> Fe <sub>20</sub> Free Layer
Pt Mn Spacer Layer
20Å Co <sub>80</sub> Fe <sub>20</sub> Biasing Layer
Pt Mn or IrMn Antiferromagnet
Underlayer
Si or Glass

FIG. 3






FIG. 5




FIG. 6